To Remove Brake Pins.

Difficulty is sometime encountered in removing brake pins which have

hecome rusty.

A C clamp, as shown in Figure 4, may be used in this work to good ad-

vantage. Place the hollow end of the C clamp over the head of the

brake pin against the head of the yoke and screw firmly.

Then tighten the cap screw against

-C. A. Bittner, Romig Auto Garage,

To Keep a Split Gear From

Slipping.

Double a piece of sand paper and wrap around the shaft in the form of

a shim to came between the shaft and the gear. The rough surface against

the gear. The rough surface against both the shaft and gear prevents the

cear from alipping.
-Chas. A. Lenz, 5:0 Fast Genesee street, .

To Tow a Ford Car With

Broken Ayle.

Tie a 2 by 4 twelve feet long or

A Convenient Car Washer. A discarded wheel rim & fastened

to the joist by means of two hanger bolts. A universal joint is placed on the pipe and the horizontal pipe is

operated on the rim by means of the hanger attached to the pulley.

The hose is then attached to the pipe and by means of the pulley which

runs around the rim the pipe can be

Figure 5 illustrates a means which

### CHECKING UP ALIGNMENT LENGTHENS LIFE OF CAR

The Fifty-sixth of a Series of Articles by an Expert for the Automobile Owner.

By WALTER SHIELDS.

If two conditions, namely perfect inbrication and perfect alignment, could
be maintained in every part of an automobile it never would wear out. The
parts runing true and never touching,
there would be no wear as we ordinarily
understand it. With the alignment once
perfect and the lubrication also we
would have the ideal piece of mechanism. However, neither condition can be
maintained all the time, and it is even
the most difficult of tasks so to manufacture a car as to get alignment closely

Whenever any unit of the car is taken
apart the owner should demand an inspection for alignment, for very often
the condition can be remedied at slight
cost. Some garage men do not know
how to align parts, which is all the more
reason why the owner should demand an inspection for alignment, for very often
the condition can be remedied at slight
cost. Some garage men do not know
how to align parts, which is all the more
reason why the owner should demand an inspection for alignment, for very often
the condition can be remedied at slight
cost. Some garage men do not know
how to align parts, which is all the more
reason why the owner should demand an inspection for alignment, for very often
the condition can be remedied at slight
cost. Some garage men do not know
how to align parts, which is all the more
reason why the owner should demand an inspection for alignment, for very often
the condition can be remedied at slight
cost. Some garage men do not know
how to align parts, which is all the more
reason why the owner should demand an inspection for alignment, for very often
the condition can be remedied at slight
cost. Some garage men do not know
how to align parts, which is all the more
reason why the owner should demand an inspection for alignment, for very often
the condition can be aligned at slight
cost. Some garage men do not know
how to align parts, which is all the more
reason why the owner should demand in
the condition can be
aligned at slight
cost. Some garage men do not kno

Just to illustrate the point I wish to make let me mention an incident that occurred recently in the largest service station in New York. An owner brought his car in, complaining of noise in the vicinity of the generator, though there were no charging and lighting troubles generally. The electrical man was put on the job and after testing the generator to removed it for testing in the shop. The generator was dismantied and it was found that the armature was burned out, all because the owner had neglected to oil the rear armature bearing. The owner admitted he did not oil it. This bearing went dry, wore excessively and permitted the armature to drop down, and scrape against the field pleces. The cost for fixing up the generator was mentioned as \$18—all because the owner neglected to spend five minutes time and a few drops of oil.

Out of alignment is first brought home to the new owner when he goes to make a tree adjustment and the adjuster in the first brought home to the new owner when he goes to make a tree adjustment and the adjuster in this kind. If there is a magneto, it was an armature which runs on two bearings. Oil neither and they wear rapidly and the armature drops down a little; oil one and one end will stay up and the armature drops down. It takes more power to drive an out of line part than it does a part running true. Perhaps this will tell many owners with the fuel of the armature which runs on two bearings. Oil neither and they want the armature drops down. It takes more power to drive an out of line part than it does a part running true. Perhaps this will tell many owners whith the fuel one and one end will stay up and the armature drops down. It takes more power to drive an out of line part than it does a part running true. Perhaps this will tell many owners why the fuel consumption is so high. Owners should consider that it is the care of the individual places that makes for an efficient whole.

In order that the flywheel correctly both units must be in alignment. If the rear crankshaft beari tire alignment is affected by a number of things, including the steering, the front axle, the wheel itself and its bear-part by part and places pointed out

seems to be to have the frame straighten the owner in many other ways. I do not know how many readers have had rear axle trouble, but it can be said with a fair decree of certainty that most of it was caused by out of alignment caused by lack of lubrication or poor driving. It is easier to harm the rear axle than most drivers imagine. Take as an instance the breakage of a differential from the machinal breaks or takes the stress and distorts accordingly. Driving over a piece of rough road recently an owner had occasion to stop suddenly. But at the moment the applied the brakes, which he did ment be applied the brakes, which he did harshly, locking the rear wheels, the rear end was up in the air. When the twheels came to the ground again they were not moving at any speed, but the car was going forward fairly fast, too fast for the road. What happened? The weakest part of the driving system took the tremendous strain, and it happened to be the driving pinion. This sort of driving throws many parts out of allantment, but the owner does not know it at the numbers. Later on year growling may tell him that something is wrong. He says the gears need oil. Perhaps they do, but often the bearings need replacement or the housing needs realignified or an axle shaft needs straightening. harshly, locking the rear wheels, the rear end was up in the air. When the wheels came to the ground again they

maintained all the time, and it is even the most difficult of tasks so to manufacture a car as to get alignment closely approaching the ideal. When a part is not running true, that is out of alignment, it means that it is not running parallel or in correct relation to the adjacent parts. Thus, if two bevel gears are correctly in mesh their axes are at \$0 degrees to one another, but if the axes are not at 30 degrees there is out of alignment. Take an ordinary paper pin wheel running at 90 degrees to its axis and tilt the wheel, you cause excessive friction and reduce its speed, because the wheel does not run in its true relation to its shaft. Now, when a car leaves the factory the parts are aligned as best is possible and well enough for the purpose, but the driver of the car can soon destroy this alignment in many parts by improper handling of the car, and by not attending to lubrication he makes matters still worse.

Just to illustrate the point I wish to make let me mention an incident that make let me mention an incident that occurred reseative in the largest service.


Out of alignment is first brought home to the new owner when he goes to make a tire adjustment and the adjuster in emphatic terms tells him that the tire is all right but the wheel is not running true. There is no denying it, for the tire tread convincingly shows this. When wheels are out of alignment it is the earlest of things to see that instead of truly rolling around they will half roll and half slide and perhaps wobble noticeably. The car goes straight ahead and the tire part ahead and part sideways, which means that that tire scrapes there often is a growling sound coming from the transmission case. Most ser as the ground and the tread gets the same sort of treatment that it would if of this is caused initially by lack of held against an emery wheel, only the lubrication, though it must be accepted grinding is not so rapid. Now the front

ing and rim. Rear tire alignment is where even strict attention to lubrication affected by the wheel and bearing rim and the axle. The cost of checking up would prevent a great deal of trouble from out of alignment. In some parts trifling compared with the tire wear, yet how many owners attend to this matter as they should.

Out of alignment is forcibly impressed to the trained and force it. But often the mere trend and force it. But often the mere trend and force it. ing and rim. Rear tire alignment is where even strict attention to lubrication

#### Great Motoring States.

#### King Eight Brougham "Custom Built."



It is quite the vogue now to have one's closed car "special cusbuilt." The King Car Corporation at Broadway and Fifty-second street is showing some of these special bodies on the regular King S chassis. The long low design, so much desired by the most particular buyers, is splendidly carried out in these cars. The King brougham-shown here sells for \$3,300.

# CLOSING OUT | HIGH CLASS SALE OF

PIERCE ARROW LQCOMOBILE CADILLAC OWEN MAGNETIC MARMON

STEARNS KNIGHT AT LESS THAN COST Painted and upholstered to suit. Belivered in a very short period. We need the room for our new Repair Department.

**AUTO** Repair Work For the war-time economist who

will renew his present car instead of buying a new one, we have established a new department where the "Royal" standard of quality will prevail.

BODY WORK PAINTING UPHOLSTERING SLIP COVERS VICTORIA TOPS AT LOW COST

ROYAL MOTOR BODY CO.,
11 WEST 19th STREET NEW YORK 211 WEST 19th STREET

TAIL

ROPE

Fig. 6-To tow a ca

FLOAT

GAS LEVEL

BUTTON

12FT 2×4

(O)

2X6 NAILED

TO INSIDE

JOIST

THIOL

RIM

Herry De Bear, the local Maxwell manager, not only believes in

votes for women but in trucks for women. When some young women

recently asked him for the use of a Maxwell truck to assist in a me-

chanical course they had inaugurated, he promptly furnished one.

and, as the photograph shows, the women "hopped to it" with .

rengeance and the truck didn't seem to mind it at all.

Fig. 3 - An easily

Apparatus for Filling An Storage Batteries.

rained at any drug store, should be fitted with a cork (D) through which pass two glass tubes (B and C). Fill the bottle with disfilled water, then insert the cork holding the tubes and attach tube (C) to bottle.

By holding the thumb over the

end of tube (B), the water will not flow. By releasing the thumb, the water will flow as required. This de-vice is illustrated in Figure 1. Robert B. Ord, Santa Barbara, Cal.

An Easily Made Carbureter Warmer.

Figure 2 illustrates a device which is coslly made and which will keep the gas in carburgter bowl warm,

A two candle nower light bulb may be connected on the lighting circuit with the switch on the instrument beard. This bulb is pinced in the fewl of the carbureter as shown in Blustration. When the car is stand-ing, during the cold weather, the switch should be turned on, thus connecting the light and keeping car-

baretor bowl warm.

-R. Wm. Bronzon, Western avenue
and Walnut street, Blue Island, Ill.

#### A Home Made Theft Alarm.

The plan illustrated in Figure 8 has

The plan illustrated in Figure 8 has been used to good advantage as a theft alarm.

A large bell is mounted under the car where it is invisible, but where it can be easily heard. This bell is operated by the battery on car and is connected to a push button placed under the cushion of the driver's sent. A switch is connected on the line, and mounted in an inconspicuous place. When the driver leaves the car he when the driver leaves the car he turns on the switch. Then if any one who is not familiar with the de-vice sits on the driver's seat, the beli-rings instantly, cailing attention to the fact that someone is tampering

Diamond, Philadelphia, Po.

MAMMEN HEADS TRUCK CO. for Market.

LIPULLEY

### Louis industrial section, but other units head is removable, inlet or exhaust be charged," will be shipped in from outside points.

Fire Commissioner Gives Notice of Meeting This Week.

HEARING ON GASOLENE.

Fire Commissioner Thomas J. Drennan sends the following: Notice is given that a public hearing will be held in Room 1124, Municipal Building, February 27, at 2:30 P. M., on he subject of the transportation and delivery of gasolene within the city limits. The following items will be considered and all interested may be heard: should the present ordinance hamended so as to allow a more extensive delivery by tank wagens and would the fire hazard thereby be materially

2. What restrictions should be placed wagons covering (a) construction of whether horse drawn or gasolene or electric driven; (c) routes to be pre-scribed; (d) whether delivery or gasolette in tank wagens should be prohibited in certain streets and districts.

This hearing will be before the Board of Hazardous Trades

How Much Money Could You Save by Having Your Delivery Freed from Trouble?

Now for All Cars

Ask these users what they know:

If you are getting less than twelve miles an hour out of your delivery wagons, you are losing time.


If you are using three teams and three drivers you are using two men and two teams too many. If you are delayed by stormy weather you are putting up with needless trouble.

Smith Form a Truck now made for all cars—gives you motor truck delivery at lower initial cost than horses—and saves you all the wasted time—needless labor—and costly inconvenience of horses.

Come in Today-Investigate.

COLE and DIXON, Inc. DISTRIBUTORS

123 West 64th Street Phone Columbus 6821 Jersey City Office- 535 Communicaw Ave. Phone Bergen 4671 Dodge Brothers Strong Factors in Truck Field.



Colt-Stratton Company, Dodge Brothers New York dealers, are meeting with success in the sale of the new Dodge Brothers' half ton commercial car and the 1 1-2 ton truck shown above. This truck which combines a Torbensen internal drive rear axie, with Dodge Brothers' power plant, retails in New York for \$1,490, with stake or express body.

### LOCATE TROUBLE BY REASONING

If the Engine "Acts Up" Give It Systematic "Once Over."

Tie a 2 by 4 twelve feet long on the outer edge of the running beard, with end projecting two or three feet behind rear wheel. Drill a hole in a piece of 2 by 6 beard so that the hub cap will pass through it. Nall this board to the 2 by 4 at the point where it crosses the hub cap. Then tie the end of the 2 by 4 armly across to the opposite side of the car frame. This arrangement, shown in Figure opposite side of the car frame.

This arrangement, shown in Figure 6, allows car to be towed at a good speed for several miles.

Percy E. Thorpe, Bentley Garage, Al.

by the strong later.

From the Strongt Later.

the piston rings.

"Having disposed of these two one must now distinguish between carburetion and ignition troubles. Prime the cylinders with gasolene through the relief valves. Crank the engine and see if it will start. If it refuses to start the ignition system is at fault.

three, but the carburction is at fault. This gives a starting point. Knowing that the carburction is at fault we pay no attention to the ignition system until we have located the difficulty. Here is where a printer. "The reason many owners of automobiles fail to locate troubles when they occur is because they take only a limited view of the problem," says William H. Stewart, Jr., president of the Stewart, Automobile School.

"Their inspection only extends to the carbureter or the ignition, and having

carbureter or the ignition, and having or leakage of pressure system, leakage looked over the few parts they do un- or valve troubles of the vacuum system. derstand they are at a loss what to do If gasolene reaches the carbureter the next. And yet there are only four requirements for an engine to start and or a weak spring, leaky inlet manifold one more to enable it to keep going unless it is overloaded.

"If trouble is in the ignition system it must also be traced step by step. There are so many different ignition systems."

A Wisconsin farmer states that would be impossible to get along with the care.

"The four conditions necessary for the engine to start are ignition, carburetion, lubrication and compression. It these are right the engine must start. Nothing can prevent it. The remaining requirement is cooling, which must be right if the engine is to run any length of time. Therefore if one is trying to get his engine started or to develop best power all five conditions must be looked after.

"If an engine refuses to start we are concerned with the first four. We crank the engine by means of the grark plug and spin the engine by means of the grark plug. If only a few sparks looked after.

"If an engine refuses to start we are concerned with the first four. We crank the engine by means of the grark plug. If only a few sparks looked after.

"If an engine refuses to start we are concerned with the first four. We crank the could is in some part com-

# OVER AUTO'S UTILITY

If it starts but stops immediately the ignition system is able to fire the mixpensable They Are in Country Use.

> The American farmer considers to passenger automobile as an indispens ble part of his farm equipment. We out the automobile the farmer would be handleapped to an extent which would seriously affect the highly importan

these facts were set forth conclusive, by farmers in their replies to the questionnaires sent out by the Haynes Aulomobile Company recently. The letter were sent to 1,000 owners picked a random from every State. The fathat approximately one-seventh of the replies were from farmers indicates to the contract of which high garde care. extent to which high grade cars are

would be impossible to get along with

## You Will Be Delighted With a Chandler Sedan

HIS handsome car, distinguished for its beautiful body A as for its famous chassis, is chosen by thousands who demand quality of construction at an uninflated price.

The Chandler sedan, seating seven, is convertible in a moment's time from a completely enclosed car to an entirely open car, or the windows may be lowered if that is desired. The body, Fisher-built, is beautifully finished. The upholstery is in durable gray cloth. The minor appointments all give the work of refinement.

And the price is much lower than you are asked to pay for cars of similar character.

SIX SPLENDID BODY TYPES

Seven-Passenger Touring Car. \$1595 Four-Passenger Roadster, \$1595 Four-Passenger Sport Model, \$1675 Convertible Sedan, \$2295 Convertible Coupe, \$2195 Limousine, \$2895

(All prices f. b. b. Cleveland)

Come Choose Your Chandler Now

# **BRADY-MURRAY MOTORS CORPORATION**

New York's Most Complete Motor Car Institution 1884 BROADWAY, at 62nd Street

FARRELL AUTO CO.
1284 Redford Ave., Brooklyn
HUBSON BOULEVARD GARAGE
Cor. Hudson Boulevard & Bergen Ave., Jersey City W. C. D. MOTOR CAR CO. 220 Central Ave., Newark CONCOURSE MOTOR CAR CO. 2100 Grand Concourse, Brons CHANDLER MOTOR CAR COMPANY, Cleveland, Ohio

BRADY-MURKAY MOTORS CORP'N